

DIRECTIONS:

For Dip/Spray Cleaning: Dilute 1 part **Copper Brite** with 10 parts water. Dilution may vary depending on specific application. Rinse with clear water.

For Dip Tanks: The recommended pH for operating use of this product is 2.00 - 2.25.

Copper Brite

Concentrated Citric Acid Cleaner

CAUTION

KEEP OUT OF REACH OF CHILDREN
Net Contents: 55 gal (208.2 L)

Copper Brite is a concentrated, citric acid based cleaner. It is biodegradable and is formulated to minimize flash oxidation.

0297-055



CAUTION
Dispose of contents/container in accordance with federal, state and local regulations.

INGREDIENTS (CAS#): Water (7732-18-5), Citric Acid (77-92-9), Surfactants.



Detco Industries, Inc.
Conway, AR
1-800-282-2133
www.detco.com