

DIRECTIONS:

General Cleaning: Dilute 1:5 to 1:10 with water and apply through spray equipment onto surface to be cleaned. Allow 3-5 minutes contact time. Do NOT allow product to dry on surface. Rinse thoroughly with water.

For specialized procedures and dilutions, contact your Detco representative.

HF Plus may cause damage to painted surfaces or galvanized metals, aluminum or other sensitive surfaces.



Detco Industries, Inc.
Conway, AR
1-800-282-2133
www.detco.com

HF PLUS

**Heavy-Duty
Chlorinated
Alkaline
Cleaner**

**High Foaming
Concentrated**

DANGER

KEEP OUT OF REACH OF CHILDREN
Net Contents: 55 gal (208.2 L)

HF Plus is a high foaming alkaline cleaner which is excellent at removing protein and fat residues. It is useful for CIP cleaning and for cleaning other food processing equipment.

DANGER

Causes severe skin burns and eye damage. Wash hands thoroughly after handling. Wear protective gloves/eye protection/protective clothing. **IF SWALLOWED:** Rinse mouth. Do NOT induce vomiting. **IF ON SKIN:** (or hair) Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. **IF INHALED:** Remove to fresh air and keep at rest in a position comfortable for breathing. Immediately call a **POISON CENTER** or doctor. **IF IN EYES:** Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Store locked up. Dispose of contents/container in accordance with federal, state and local regulations.

INGREDIENTS (CAS#): Water (7732-18-5), Potassium Hydroxide (1310-58-3), Sodium Hypochlorite (7681-52-9), Surfactant (68479-04-9), Sodium Metasilicate (6834-92-0).



0891-055

