

SAFETY DATA SHEET



Date Prepared : 03/26/2015
MSDS No : 0417

DC Mist - Cotton

1. PRODUCT AND COMPANY IDENTIFICATION

PRODUCT NAME: DC Mist - Cotton
GENERAL USE: Air Freshener
PRODUCT CODE: 0417

MANUFACTURER

Detco Industries, Inc.
PO Box 430
Conway, AR 72033
Product Stewardship: (800) 282-2133

24 HR. EMERGENCY TELEPHONE NUMBERS

CHEMTREC (US Transportation) :(800) 424 - 9300

2. HAZARDS IDENTIFICATION

GHS CLASSIFICATIONS

Health:

Eye Irritation, Category 2B

Physical:

Flammable Aerosols, Category 1
Liquefied Gases

GHS LABEL



Flame



Gas
cylinder

SIGNAL WORD: DANGER

HAZARD STATEMENTS

H222: Extremely flammable aerosol.
H280: Contains gas under pressure; may explode if heated.
H320: Causes eye irritation.

PRECAUTIONARY STATEMENT(S)

Prevention:

P210: Keep away from heat/sparks/open flames/hot surfaces. – No smoking.
P211: Do not spray on an open flame or other ignition source.
P251: Pressurized container: Do not pierce or burn, even after use.
P264: Wash hands thoroughly after handling.

Response:

P305+P351+P338: IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
P337+P313: If eye irritation persists: Get medical advice/attention.

Storage:

P410: Protect from sunlight.
P412: Do not expose to temperatures exceeding 50°C/ 122°F.

SAFETY DATA SHEET



Date Prepared : 03/26/2015
MSDS No : 0417

DC Mist - Cotton

P403: Store in a well-ventilated place.

3. COMPOSITION / INFORMATION ON INGREDIENTS

Chemical Name	Wt. %	CAS
Propane/isobutane	10 - 30	68476-86-8
Acetone	60 - 100	67-64-1
Proprietary Fragrance	1 - 10	mixture

4. FIRST AID MEASURES

EYES: Flush eyes with water for at least 15 minutes. If pain and/or irritation persists, get medical attention.

SKIN: Flush affected area with water for 15 minutes. Remove contaminated clothing. If pain and/or irritation persists, get medical attention. Launder clothes before reusing.

INGESTION: Do not induce vomiting. Give 2 glasses of water. Get immediate medical attention.

INHALATION: Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Get medical attention.

5. FIRE FIGHTING MEASURES

GENERAL HAZARD: Fire exposed containers may rupture.

EXTINGUISHING MEDIA: Carbon dioxide, water fog, foam or dry chemical. Do not use water jet as an extinguisher, as this will spread the fire.

FIRE FIGHTING PROCEDURES: As in any fire, wear self-contained breathing apparatus pressure-demand, (MSHA/NIOSH approved or equivalent) and full protective gear.

6. ACCIDENTAL RELEASE MEASURES

SMALL SPILL: Remove all sources of ignition. Contain spill. Absorb liquid and place in sealed container for disposal.

7. HANDLING AND STORAGE

GENERAL PROCEDURES: Store as Level 3 Aerosol (NFPA 30B)

STORAGE: Keep away from sources of ignition. Do not store at temperatures above 120F.

8. EXPOSURE CONTROLS / PERSONAL PROTECTION

SAFETY DATA SHEET



Date Prepared : 03/26/2015
MSDS No : 0417

DC Mist - Cotton

EXPOSURE GUIDELINES

OSHA HAZARDOUS COMPONENTS (29 CFR1910.1200)							
		EXPOSURE LIMITS					
		OSHA PEL		ACGIH TLV		Supplier OEL	
Chemical Name		ppm	mg/m ³	ppm	mg/m ³	ppm	mg/m ³
Acetone	TWA	1000 ppm ^[1]	2400 mg/m ³ ^[1]	500 ppm	mg/m ³	NL ppm	NL mg/m ³
	STEL	ppm	mg/m ³	750 ppm	mg/m ³	NL ppm	NL mg/m ³
Footnotes:							
1. NL = Not Listed							

PERSONAL PROTECTIVE EQUIPMENT

EYES AND FACE: Wear safety glasses with side shields (or goggles).

SKIN: Wear rubber or nitrile gloves.

RESPIRATORY: None.

PROTECTIVE CLOTHING: None.

9. PHYSICAL AND CHEMICAL PROPERTIES

PHYSICAL STATE: Aerosol-Pressurized Liquid/Gas

ODOR: Linen

COLOR: Colorless

pH: NA = Not Applicable

FLASHPOINT AND METHOD: Extremely Flammable Aerosol

FLAMMABLE LIMITS: N/D to N/D

VAPOR PRESSURE: < 180 mmHg at 21°C (70°F)

VAPOR DENSITY: < 2 (Air=1)

BOILING POINT: Not Determined

FREEZING POINT: Not Determined

SOLUBILITY IN WATER: Insoluble

EVAPORATION RATE: > 3

SPECIFIC GRAVITY: 0.78 to 0.81

Notes: Concentrate Only.

(VOC): < 30.000 %

COEFF. OIL/WATER: Not Determined

10. STABILITY AND REACTIVITY

HAZARDOUS POLYMERIZATION: Will not occur.

STABILITY: Stable.

CONDITIONS TO AVOID: Temperatures above 120F, heat, flame and sources of ignition.

SAFETY DATA SHEET



Date Prepared : 03/26/2015
MSDS No : 0417

DC Mist - Cotton

HAZARDOUS DECOMPOSITION PRODUCTS: Oxides of carbon.

INCOMPATIBLE MATERIALS: Strong oxidizing agents, strong reducing agents, some plastics.

11. TOXICOLOGICAL INFORMATION

CARCINOGENICITY

Notes: None known.

12. ECOLOGICAL INFORMATION

ECOTOXICOLOGICAL INFORMATION: Not Available

13. DISPOSAL CONSIDERATIONS

DISPOSAL METHOD: Dispose of in accordance with federal, state and local regulations.

14. TRANSPORT INFORMATION

DOT (DEPARTMENT OF TRANSPORTATION)

PROPER SHIPPING NAME: Aerosols, Ltd. Qty.

PRIMARY HAZARD CLASS/DIVISION: 2.1

UN/NA NUMBER: 1950

PACKING GROUP: N/A

15. REGULATORY INFORMATION

UNITED STATES

SARA TITLE III (SUPERFUND AMENDMENTS AND REAUTHORIZATION ACT)

FIRE: Yes

CERCLA (COMPREHENSIVE RESPONSE, COMPENSATION, AND LIABILITY ACT)

Chemical Name	Wt. %	CERCLA RQ
Acetone	60 - 100	5,000


16. OTHER INFORMATION

PREPARED BY: E. Spicer **Date Prepared:** 03/26/2015

HMIS RATING

HEALTH	<input type="checkbox"/>	1
FLAMMABILITY	<input type="checkbox"/>	3
PHYSICAL HAZARD	<input type="checkbox"/>	0
PERSONAL PROTECTION	<input type="checkbox"/>	A

NFPA CODES



MANUFACTURER DISCLAIMER: The information provided in this Safety Data Sheet has been obtained from

SAFETY DATA SHEET



Date Prepared : 03/26/2015
MSDS No : 0417

DC Mist - Cotton

sources believed to be reliable. Manufacturer provides no warranties, either expressed or implied and assumes no responsibility for the accuracy or completeness of the data contained herein.