

DIRECTIONS:

Recirculating Cleaner/CIP Systems:
Charge system with product. Use 1.5 to 3.6 oz of product per gallon of water in system. Recirculate product for 1-4 hours, empty, then flush with clean water.

For specialized procedures and dilutions, contact your Detco representative.

CIP Plus may cause damage to painted surfaces or galvanized metals, aluminum or other sensitive surfaces.

CIP PLUS

Heavy-Duty Alkaline Cleaner

Low Foaming

Concentrated

DANGER

KEEP OUT OF REACH OF CHILDREN
Net Contents: 55 gal (208.20 L)

CIP Plus is an alkaline cleaner containing sodium hypochlorite which is excellent at removing protein residues. It is useful for CIP cleaning and for cleaning evaporation units.

DANGER

Causes severe skin burns and eye damage.
Wash hands thoroughly after handling. Wear protective gloves/eye protection/protective clothing. IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. IF ON SKIN:(or hair) Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF INHALED: Remove to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Store locked up. Dispose of contents/container in accordance with federal, state and local regulations.

INGREDIENTS (CAS#): Water (7732-18-5), Potassium Hydroxide (1310-58-3), Sodium Hypochlorite (7681-52-9)



0254-055



Detco Industries, Inc.
Conway, AR
1-800-282-2133
www.detco.com