

**DIRECTIONS:**  
DO NOT ALLOW PRODUCT TO DRY ON SURFACE.

**Pressure Washing:** Dilute 20:1 with water, adjusting dilution as needed. Allow to soak for 2-3 minutes, then rinse thoroughly with water.

**Degreasing Engines and Machinery:** Dilute 15:1 to 20:1 with water, adjusting dilution as needed. Allow to soak for 1-3 minutes, then rinse thoroughly with water.

**Concrete Shop Floors:** Dilute with 8 oz per gallon of water. Soak floor with solution, scrub if needed, remove solution with squeegee/wet vac, then rinse well.

**Soak Cleaning:** Mix 1 to 2 cups of Detco 109 per gallon of water in tank. (Tank may be heated to 180 degrees F if desired) Do NOT use with aluminum, galvanized steel or other non-ferrous metals.

# DETCO 109

## Heavy-Duty Cleaner & Degreaser with Butyl

### Non-Phosphate

**DANGER**  
KEEP OUT OF REACH OF CHILDREN  
Net Contents: 55 gal (208.2 L)

**Detco 109** is a non-phosphate, heavy-duty, industrial strength cleaner and degreaser. It will remove grease, oil, dirt and other soils quickly and effectively.

**DANGER**  
Causes severe skin burns and eye damage.  
Wash hands thoroughly after handling.  
Wear protective gloves/eye protection.  
**IF SWALLOWED:** Rinse mouth. Do NOT induce vomiting. **IF ON SKIN:** Remove/Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. **IF INHALED:** Remove to fresh air and keep at rest in a position comfortable for breathing. Immediately call a POISON CENTER or doctor. **IF IN EYES:** Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Store locked up. Dispose of contents/container in accordance with federal, state and local regulations.



0513-055



0 21855 05131 3

**Detco Industries, Inc.**  
Conway, AR  
1-800-282-2133  
[www.detco.com](http://www.detco.com)

